

## Update on Exide Technologies

### Fishburn ES

Sample Location: SCH-13-1D

Temporary fencing was installed and the front lawn on the east side was reseeded on 8/8/16.



Sample Location: SCH-13-2D

Temporary fencing was installed and the front lawn on the east side was reseeded on 8/8/16.



**Rowan ES**

Sample Location: SCH-09-3D

Temporary fencing was installed on the west side of the school. Needs to be reseeded.



Sample Location: SCH-09-3D

Mulch was added around the tree wells on the west side. Needs to be reseeded.




Sample Location: SCH-09-4D

Temporary fencing was installed, limiting access to the planting area adjoining a classroom building.



Sample Location: SCH-09-1D

Temporary fencing was installed and mulch was added around the tree well located at the southeast portion of the playground.



**Lorena ES**

Sample Location: SCH-07-2D

Temporary fencing was installed around the exterior lawn on the east side of the school. This area needs to be reseeded.



Sample Location: SCH-07-3D

Temporary fencing was installed around the exterior lawn on the east side of the school. This area needs to be reseeded.

